

Annexure D

BUILDING SAFETY CERTIFICATE

No. S12

Dated: 26.09.24

It is certified that the existing building, Global Indian International School at 215 & 216, PH. No. 04, Near Canara Bank, Lava, Nagpur, Maharashtra 440023 is having block(s) Floor(s) as per details below:

Details of Block(s) in the School	Block 1	Block 2	Block 3	Block 4	Block 5	Block 6
No. of Floor(s) in the block	Ground Floor + First Floor+ Second Floor + Third Floor (G+3)	Ground Floor + First Floor+ Second Floor + Third Floor (G+3)				

The building is owned/occupied by Global Indian International School have complied with the Building Safety requirements in accordance with the National Building Code Rules and verified by Jagruati Nitin Zode, A.E.-I.....The officer concerned of NMRDA (Nagpur Metropolitan Region Development Authority, Nagpur) on26.09.2024.....in the presence of Ms. Nidhi Gupta, Principal Global Indian International School and the building /premises is fit for occupancy upto Classes XII for running school with effect from ...26.09.2024...for a period of 20 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School should have proper ongoing maintenance of the building.
2. School should regular inspection of school infra maintenance work and premises.
3. School should compliance with building safety standards.
4. School should upkeep of essential services related to school infrastructure.

Issued on26.09.24..... at.....Nagpur.....by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with seal :

Jagruati N. Zode
A.E.-I (M-I), NMRDA

Name : Jagruati Nitin Zode

Designation : Assistant Engineer-I

Name & Address of the Department : NMRDA HQ, station Road, Sadar, Nagpur

Nidhi Gupta

NIDHI GUPTA
Digitally signed by NIDHI GUPTA
Date: 2025.08.21 13:33:53 +05'30'

Sivankutty
Sivankutty Janardhanan Nair
Digitally signed by Sivankutty Janardhanan Nair
Date: 2025.08.04 15:08:04 +05'30'